



RELATÓRIO DA AMOSTRA

PROCESSO Nº 0234/2021
OFERTA DE COMPRA Nº: 892000801002021OC00042
MODALIDADE: PREGÃO ELETRÔNICO Nº 025/CPB/2021.

DENOMINAÇÃO DO OBJETO

Constituição de Sistema de Registro de Preços para Prestação de Serviços na Produção de Materiais Gráficos, conforme especificações constantes do Termo de Referência, Anexo I.

No dia 28 de julho de 2021, o Departamento de Tecnologia da Informação do Comitê Paralímpico Brasileiro, analisou a amostra recebida, contendo descritivo das configurações do material ofertado, tendo como parâmetro o Anexo I, Termo de Referência.

LICITANTE AVALIADA

Licitante: YUMA COMERCIAL EIRELI - ME

LOTE ÚNICO

ITEM	ESPECIFICAÇÃO	RESULTADO
01	Access Point Cisco 3702I AIR-CAP3802I-Z-K9	Aprovado
02	Licença para Cisco 2500 Wireless LIC-CT2504 –	Aprovado

RELATÓRIO FOTOGRÁFICO

EMPRESA: YUMA COMERCIAL EIRELI - ME

LOTE UNICO – ITEM 1 - 2

```
COM5 - Tera Term VT
File Edit Setup Control Window Help
[*07/28/2021 22:32:37.3987] CAPWAP State: Image Data
[*07/28/2021 22:32:37.4293] do NO_UPGRADE, part2 is active part
[*07/28/2021 22:32:37.4355]
[*07/28/2021 22:32:37.4355] CAPWAP State: Configure
[*07/28/2021 22:32:37.4386] NO-ENC-PROVIDER for DOT11R_WLC_MAC_IP_PAYLOAD
[*07/28/2021 22:32:38.1854] Started Radio 0
[*07/28/2021 22:32:38.2023] DOT11_DRV[0]: set_channel Channel set to 1
[*07/28/2021 22:32:39.0886] DOT11_DRV[0]: set_channel Channel set to 1
[*07/28/2021 22:32:40.3180] Started Radio 1
[*07/28/2021 22:32:40.3407] DOT11_DRV[1]: set_channel Channel set to 36
[*07/28/2021 22:32:41.2559] DOT11_DRV[1]: set_channel Channel set to 36
[*07/28/2021 22:32:42.5158] Discarding msg CAPWAP_WTP_EVENT_REQUEST(type 9) in CAPWAP state: Configure(8).
[*07/28/2021 22:32:42.5159] Discarding msg CAPWAP_WTP_EVENT_REQUEST(type 9) in CAPWAP state: Configure(8).
[*07/28/2021 22:32:42.5159] Discarding msg CAPWAP_WTP_EVENT_REQUEST(type 9) in CAPWAP state: Configure(8).
[*07/28/2021 22:32:42.5160] Discarding msg CAPWAP_WTP_EVENT_REQUEST(type 9) in CAPWAP state: Configure(8).
[*07/28/2021 22:32:42.5160] Discarding msg CAPWAP_WTP_EVENT_REQUEST(type 9) in CAPWAP state: Configure(8).
[*07/28/2021 22:32:42.6852] DOT11_DRV[0]: set_channel Channel set to 1
[*07/28/2021 22:32:43.6978] DOT11_DRV[1]: set_channel Channel set to 36
[*07/28/2021 22:32:44.6143] DOT11_DRV[1]: set_channel Channel set to 36
[*07/28/2021 22:32:45.7693]
[*07/28/2021 22:32:45.7693] CAPWAP State: Run
[*07/28/2021 22:32:45.7993] CAPWAP HW tunnel params changed, UPDATING the existing
[*07/28/2021 22:32:45.8580] AP has joined controller Controller_WLAN_CPB

Password:
% Authentication failed

User Access Verification
Username:
Username: 
```




```

AP70DB.98E1.22C8#show capwap
  client      CAPWAP Client Information
  ids         CAPWAP IDS Information
  ip          CAPWAP IP configuration
  location    CAPWAP location Information
  mcast       CAPWAP Mcast Information
  pnpinfo     PNP Information
  traffic     CAPWAP Traffic Information
AP70DB.98E1.22C8#show capwap ip
  config      CAPWAP IP static configuration
AP70DB.98E1.22C8#show capwap ip config
IP Address                : 172.20.7.2
IP netmask                 : 255.255.255.128
Default Gateway            : 172.20.7.126
AP70DB.98E1.22C8#

```

CISCO									
	MONITOR	WLANs	CONTROLLER	WIRELESS	SECURITY	MANAGEMENT	COMMANDS	HELP	FEEDBACK
Wireless									
Access Points									
All APs									
Radios									
802.11a/n/ac									
802.11b/g/n									
Dual-Band Radios									
Global Configuration									
Advanced									
Mesh									
ATF									
RF Profiles									
FlexConnect Groups									
FlexConnect ACLs									
FlexConnect VLAN									
Templates									
OEAP ACLs									
Network Lists									
802.11a/n/ac									
802.11b/g/n									
Media Stream									
Application Visibility									
And Control									
Country									
Timers									
Netflow									
QoS									
	AP-DESCANSO-ATLETAS			172.20.7.67					AIR-CAP37021-A-K9
	AP-GOVERNANCA			172.20.7.63					AIR-CAP17021-Z-K9
	AP-33			172.20.7.38					AIR-CAP17021-Z-K9
	AP-21			172.20.7.50					AIR-CAP17021-Z-K9
	AP-HOTEL1B-4			172.20.7.43					AIR-CAP17021-Z-K9
	AP-HOTEL1A-2			172.20.7.62					AIR-CAP17021-Z-K9
	AP-HOTEL1B-1			172.20.7.41					AIR-CAP17021-Z-K9
	APf44e.0564.6ab4			172.20.7.15					AIR-CAP37021-A-K9
	AP-35			172.20.7.36					AIR-CAP17021-Z-K9
	AP-MARKETING			172.20.7.72					AIR-CAP17021-Z-K9
	AP-INDOOR2			172.20.7.21					AIR-CAP37021-A-K9
	AP-18			172.20.7.53					AIR-CAP17021-Z-K9
	AP-PISCINA			172.20.7.18					AIR-CAP17021-Z-K9
	AP-MODALIDADES			172.20.7.33					AIR-CAP17021-Z-K9
	AP-DITEC			172.20.7.24					AIR-CAP17021-Z-K9
	AP-HOTEL-SLJOGOS			172.20.7.64					AIR-CAP17021-Z-K9
	AP-17			172.20.7.54					AIR-CAP17021-Z-K9
	AP-REUNIAO-SUAFC			172.20.7.48					AIR-CAP17021-Z-K9
	AP-HOTEL1B-2			172.20.7.71					AIR-CAP17021-Z-K9
	AP-HOTEL2A-4			172.20.7.69					AIR-CAP17021-Z-K9
	AP-HOTEL2B-2			172.20.7.10					AIR-CAP37021-A-K9
	AP-HOTEL1A-3			172.20.7.47					AIR-CAP17021-Z-K9
	AP-BOCHA-23			172.20.7.23					AIR-CAP37021-A-K9
	AP-27			172.20.7.44					AIR-CAP17021-Z-K9
	AP-HOTEL2A-1			172.20.7.56					AIR-CAP17021-Z-K9
	AP70DB.98E1.22C8			172.20.7.2					AIR-AP38021-Z-K9



As imagens acima demonstram após atualização da Firmware da Controladora Cisco, a amostra configurada, conectada e sincronizada na controladora, disponibilizando assim as redes Wi-Fi do CPB.

Danillo Vieira Nascimento
DETI – Departamento de Tecnologia da Informação
Comitê Paralímpico Brasileiro